

Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722 CCTV-01979490147, Web team- 01979999711

HOME অনলাইনে অর্ডার করতে ভিজিট করুন www.munshiganjit.com.bd

A Super Store Of Computer & Electronics Accessoriess MITCare- 01979490145, Warranty-01979490146

194, Banghabandhu Road, Shomobay New Market (2nd Floor) Shop No. 117-118,103-104, Chasara, Narayanganj-1400 www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd



OUR SHOP SHOP Shop No-39, Level-4, Kassaf Shopping Center, Chittagong Road, Siddhirganj, Narayanganj



29 DIT plot, Balur mat, 4th floor, Razzak villa, Chashara, Narayanganj



194, Banghabandhu Road, Shomobay New Market (2nd Floor)

KSTAR 2000VA Offline UPS



Sale Price: 14000.0

PRODUCT ID: 03751

B 4				
 N	laır	ı Fe	atu	re

Capacity	2000VA
Load Capacity	1200W
Input Voltage	140-300V
Output Voltage	230V
Frequency (Battery Mode)	50HZ - 60HZ
Noise Level	<45DB

Input Features

Frequency	50HZ - 60HZ
Voltage Range	140-300V

Output Features

Backup Time	7 - 20 Minutes (with full load)
Voltage Range	230V
Type of Wave	Sine Wave(mains), Square Wave (Inverter)
Transfer Time	4-8ms

Physical

Specification

Manufacture

Warranty



Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722 MITCare- 01979490145, Warranty-01979490146 CCTV-01979490147, Web team- 01979999711

A Super Store Of Computer & Electronics Accessoriess 194, Banghabandhu Road, Shomobay New Market (2nd Floor)

Shop No. 117-118,103-104, Chasara, Narayanganj-1400 www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd





Shop No-39, Level-4, Kassaf Shopping Center, Chittagong Road, Siddhirganj, Narayanganj



29 DIT plot, Balur mat, 4th floor, Razzak villa, Chashara, Narayanganj



194, Banghabandhu Road, Shomobay New Market (2nd Floor)

Main Feature

Warranty

01-Year Warranty

Under the following conditions, the warranty would not be provided:

- UPS burning due to thunder, abnormal overload, insect entrance and others.
- If ambient temperature should not be maintained at 20 to 26 degrees Celsius with proper dehumidification. (24/7)
- If the product is placed in a dusty and damp place.
- In the absence of Generator connectivity Without proper battery charge, the warranty will be void.
- Battery swelling and overcharging due to the wrong system voltage setting of the UPS.