


Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722 A Super Store Of Computer & Electronics Accessoriess MITCare- 01979490145, Warranty-01979490146 CCTV-01979490147, Web team- 01979999711

HOME অনলাইনে অর্ডার করতে ভিজিট করুন www.munshiganjit.com.bd

194, Banghabandhu Road, Shomobay New Market (2nd Floor) Shop No. 117-118,103-104, Chasara, Narayanganj-1400

www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd





194, Banghabandhu Road, Shomobay New Market (2nd Floor)









MaxGreen MG-LI-EAP-650VA 650VA Offline UPS



Sale Price: 3400.0

PRODUCT ID: 04263

N 4 -	•	1	
 $1 \times 1 \sim$	บา	Feati	IIro

- Main Feature			
Capacity	650VA		
Input Voltage	220Vac		
Output Voltage	220Vac		
Frequency (Battery Mode)	50Hz ± 1Hz		
Noise Level	Less than 40dB		
Battery	Internal maintenance-free lead-acid(12V/7/7.5Ah*1)		
Alarm	Battery mode- Sounding every 10 seconds Low battery- Sounding every 10 seconds Overload - Sounding every 10 seconds Battery Replacement - Alarm Sounding every 10 seconds Fault- Continuously sounding		
Indications	Line Mode Green lighting ,Battery Mode Yellow Lighting ,Fault Red Lighting		
Input Features			
Frequency	50 Hz		

Frequency	50 Hz
Voltage Range	140-290VAC

Output Features

Backup Time	up to 30 minutes
Type of Wave	Simulated Sine Wave (Bat Mode)
Transfer Time	Typical 2-6ms

Manufacture

Warranty



Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722 MITCare- 01979490145, Warranty-01979490146 CCTV-01979490147, Web team- 01979999711

A Super Store Of Computer & Electronics Accessoriess 194, Banghabandhu Road, Shomobay New Market (2nd Floor)

Shop No. 117-118,103-104, Chasara, Narayanganj-1400 www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd





Shop No-39, Level-4, Kassaf Shopping Center, Chittagong Road, Siddhirganj, Narayanganj



29 DIT plot, Balur mat, 4th floor, Razzak villa, Chashara, Narayanganj



194, Banghabandhu Road, Shomobay New Market (2nd Floor)

Main Feature

Warranty

01-Year Warranty

Under the following conditions, the warranty would not be provided:

- UPS burning due to thunder, abnormal overload, insect entrance and others.
- If ambient temperature should not be maintained at 20 to 26 degrees Celsius with proper dehumidification. (24/7)
- If the product is placed in a dusty and damp place.
- In the absence of Generator connectivity Without proper battery charge, the warranty will be void.
- Battery swelling and overcharging due to the wrong system voltage setting of the UPS.