

# Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722 CCTV-01979490147, Web team- 01979999711

# HOME অনলাইনে অর্ডার করতে ভিজিট করুন www.munshiganjit.com.bd

A Super Store Of Computer & Electronics Accessoriess MITCare- 01979490145, Warranty-01979490146

194, Banghabandhu Road, Shomobay New Market (2nd Floor) Shop No. 117-118,103-104, Chasara, Narayanganj-1400 www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd



Shop No-39, Level-4, Kassaf Shopping Center, Chittagong Road, Siddhirganj, Narayanganj



29 DIT plot, Balur mat, 4th floor, Razzak villa, Chashara, Narayanganj

Sale Price: 1.0



194, Banghabandhu Road, Shomobay New Market (2nd Floor)







PRODUCT ID: 04973

## Main Feature

Load Capacity	700W
Input Voltage	140-300V
Output Voltage 2	220-230 VAC +/-10%
Frequency (Battery Mode)	50Hz +/-1%
Noise Level	<40dB

#### Input Features

Voltage Range 140-300V

#### **Output Features**

Backup Time 8-30 Min. (Depending on load) Type of Wave Pure Sine wave

#### **Physical**

### Specification

Dimension	320 x 130 x 182 mm
Weight	8.2 Kg

#### Manufacture

#### Warranty



# Hotline-09614-502244

Sales-01979490143, Corporate- 01979999722 MITCare- 01979490145, Warranty-01979490146 CCTV-01979490147, Web team- 01979999711

## A Super Store Of Computer & Electronics Accessoriess 194, Banghabandhu Road, Shomobay New Market (2nd Floor)

Shop No. 117-118,103-104, Chasara, Narayanganj-1400 www.munshiganjit.com.bd e-mail-info@munshiganjit.com.bd





Shop No-39, Level-4, Kassaf Shopping Center, Chittagong Road, Siddhirganj, Narayanganj



29 DIT plot, Balur mat, 4th floor, Razzak villa, Chashara, Narayanganj



194, Banghabandhu Road, Shomobay New Market (2nd Floor)

#### Main Feature

Warranty

01-Year Warranty

Under the following conditions, the warranty would not be provided:

- UPS burning due to thunder, abnormal overload, insect entrance and others.
- If ambient temperature should not be maintained at 20 to 26 degrees Celsius with proper dehumidification. (24/7)
- If the product is placed in a dusty and damp place.
- In the absence of Generator connectivity Without proper battery charge, the warranty will be void.
- Battery swelling and overcharging due to the wrong system voltage setting of the UPS.